



SCHEMATIC DIAGRAM

Studioworks77i



IMPORTANT SAFETY NOTICE

THE SYMBOL MARK OF THIS SCHEMATIC DIAGRAM INCORPORATES SPECIAL FEATURES IMPORTANT FOR PROTECTION FROM X-RADIATION, FIRE AND ELECTRICAL SHOCK HAZARDS. WHEN SERVICING IT IS ESSENTIAL THAT ONLY MANUFACTURER SPECIFIED PARTS BE USED FOR THE CRITICAL COMPONENTS IN THE SYMBOL MARK OF THE SCHEMATIC.

	DPMS	DPMF	WATT
NORMAL	H	L	NORMAL
SUSPEND	L	H	HEATER ON
OFF	L	H	HEATER OFF

